

### Appendix 13 – Life Buoys

Street	Parish	Easting	Northing	Item Identity Code	Location Description
Churchill Barrier No. 1	Holm	348427.94	1001078.34	LF1	Southbound Carriageway
Churchill Barrier No. 1	Holm	348451.41	1000854.97	LF2	Northbound Carriageway
Churchill Barrier No. 2	Holm	348076.43	999786.77	LF3	Southbound Carriageway
Churchill Barrier No. 2	Holm	347964.32	999663.49	LF4	Northbound Carriageway
Churchill Barrier No. 3	Burray	347349.93	998571.22	LF5	Southbound Carriageway
Churchill Barrier No. 3	Burray	347374.04	998465.5	LF6	Northbound Carriageway
Churchill Barrier No. 4	South Ronaldsay	347929.61	995296.52	LF7	Northbound Carriageway
Churchill Barrier No. 4	South Ronaldsay	347806.18	995116.72	LF8	Northbound Carriageway